Miller DL and Durden FL. J Sur Re Rep:1000105 doi.org/10.47378/JSRR/2022.3.105

Research Article Open Access

# Biosynthetic Material Reconstruction of the Costal Arch after Tumor Resection

(Running Head: Biosynthetic Material Reconstruction)

### Daniel L. Miller, MD\*1, Fredrick L. Durden, MD2

<sup>1</sup>Section of Thoracic Surgery, Department of Surgery Medical College of Georgia at Augusta University, Augusta, GA <sup>2</sup>Section of Plastic Surgery, Department of Surgery CTCA-ATL, Newnan, Georgia

\*Corresponding author: Daniel L. Miller, MD, Section of Thoracic Surgery, Department of Surgery Medical College of Georgia at Augusta University, Augusta, GA. Email: danmiller@augusta.edu

**Citation:** Miller DL and Durden FL (2022) Biosynthetic Material Reconstruction of the Costal Arch after Tumor Resection. J Sur Re Rep: JSRR-105.

Received Date: 24th June, 2022; Accepted Date: 07th July, 2022; Published Date: 14th July, 2022

**Copyright:** © 2022 Miller DL. This is an open-access article distributed under the terms of the Creative Commons attribution License, which permits unrestricted use, distribution, and reproduction in any medium, provided the original author and source are credited.

#### **Abstract**

Reconstruction of the lower chest wall and costal arch after tumor resection can be a challenge. The perfect material does not exist to restore normal chest wall stability and mechanics. We describe a case of chest wall resection of a massive chondrosarcoma tumor involving ribs 8-10, costal arch and portion of the diaphragm. Chest wall reconstruction (CWR) was performed with a combination of biosynthetic materials (BSM) composed of ovine-derived extracellular matrix/monofilament polypropylene patch and absorbable polylactic acid (PLA) bars.


## Introduction

Biosynthetic materials (BSM) incorporate both biologic and synthetic components, which have been shown to be effective in reconstruction of abdominal clean contaminated and contaminated wounds (1,2). The principal goal of the combination material is to establish a scaffold for tissue ingrowth in addition to maintaining integrity with a permanent synthetic support. This case report describes our initial experience with a new BSM for CWR that is composed of ovine-derived extracellular matrix/ monofilament polypropylene suture in combination with PLA bars.

#### **Case Report**

A 58-year-old women noticed an asymptomatic mass in a left lower rib in 2010; patient had no history of trauma or cancer. CT scan showed a mass in the 9th rib (Figure 1). She elected no treatment at that time. The mass grew over two years. A CT scan of the chest and upper abdomen showed enlargement of the mass with no signs of metastasis (Figure 1); needle biopsy revealed a low-grade chondrosarcoma. She elected not to proceed with recommended surgical resection. The patient returned 8 years later with a massive lower chest wall mass (Figure 1), complaining of pain and dyspnea on exertion. Work-up showed no signs of metastatic disease except a new calcified nodule (8 mm) in the left lower lobe (LLL) of her lung (Figure 1).


J Sur Re Rep, 2022 Volume 1 (3) | 1 of 4



**Figure 1:** (A-D) CT scans of chest over 10 years showing enlargement of the left lower chest wall mass arising from the 9<sup>th</sup> rib initially. (E) Development of an indeterminate pulmonary nodule (red circle) within the left lower lobe.

The mass was involving ribs 8-10 and the costal arch of the left lower chest (Figure 1). Patient underwent complete resection of the mass (22.5 x 16 x 11 cm) (Figure 2) en bloc with ribs 8-10, costal arch of the left lower chest, and portion of diaphragm as well as wedge excision of the LLL nodule. Tumor was a well differentiated chondrosarcoma with all margins > 2 cm. The LLL nodule was a calcified granuloma.

Reconstruction was completed with a scaffolding of absorbable PLA bars (10) and an ovine rumen matrix patch. The PLA bars (Figure 2) were secured to ribs, intercostal muscles, and residual diaphragm first for chest wall stability and then the ovine patch (Figure 2) over the PLA bars for added stability and reestablishing integrity of the chest.



**Figure 2:** (A) PLA (BioBridge®) bars sutured to ribs and diaphragm. (B) Placement of large BSM (Ovitex®) patch for CWR. (C) Ovine extracellular matrix/monofilament polypropylene patch containing four layers of ovine rumen embroidered together into a single layered patch.

Patient refused omental or muscle interposition patch coverage. The chest cavity was drained with a 28 Fr chest tube and 10 Fr Jackson Pratt drains over the patch site. Analgesia was provided by a thoracic cavity field block with diluted bupivacaine liposome (20cc) (Exparel - Pacira Pharmaceuticals, Inc - Parsippany, NJ) as an injectable suspension with 0.25% Marcaine without epinephrine (60cc) and injectable saline (220cc) for a total volume of 300cc; multimodality pain regiment of scheduled

intravenous muscle relaxants, anti-inflammatory drugs and as needed low dose oral narcotics was used. The patient was discharged on POD 5 with JPs in place. The patient underwent reoperation for incisional dehiscence 6 weeks after CWR with advancement of an inferior latissimus flap and primary closure without sequelae; the BSM and PLA bars were intact and not removed. At 12 months follow-up, the patient had no paradoxical motion, chest wall instability or loss of abdominal integrity and no signs of recurrence or metastasis (Figure 3).

J Sur Re Rep, 2022 Volume 1 (3) | 2 of 4



**Figure 3:** 12-month follow-up CT scans of chest showing no recurrence with near-normal reconfiguration of left lower chest wall and costal arch. (A) Axial section CT scan of the chest showing near normal chest configuration. (B) Coronal section CT scan of chest showing reconstruction of the lower chest wall and costal arch. (C) 3-D reconstruction CT scan of chest showing the PLA bars in place.

Preoperative pictures of the tumor and a postoperative incisional picture are shown (Figure 4).



Figure 4: Pictures of the tumor (A, B) preoperatively and (C) c/ds<d intraoperative incision after CWR.

## **Comment**

CWR can be a challenge because the ideal reconstruction material does not exist. Universal criteria for material selection include, but are not limited to non-carcinogenicity, chemical inertness, resistance to mechanical stress, sterility, unresponsiveness to body and tissue fluids, limitation of foreign-body reactions, modifiable in size, and non-allergenic (3). Understanding patient comorbidities, potential for infection, and how the material will incorporate at a cellular level will increase success, avoid surgical morbidity, and improve long-term outcomes (4).

The CWR material used was a BSM patch (Ovitex® reinforced tissue matrix; TELA Bio, Inc, Malvern, PA), made of four-layers of ovine rumen mucosa incorporated into a single layer with interwoven and embroidered polymer fibers (polypropylene); the patch was secured under tension with running and interrupted polypropylene sutures over the PLA bars (BioBridge®; Acumed, Inc - Hillsboro, OR) that were secured together with 0 silk ties and #1 non-absorbable polyester sutures to create extended doublets to bridge the defect. The PLA bars were secured to the ribs, intercostal muscles, and residual diaphragm with #1

J Sur Re Rep, 2022 Volume 1 (3) | 3 of 4

non-absorbable polyester suture under tension to prevent loss of lower chest and abdominal domain. The BSM patch established a scaffold for tissue ingrowth in addition to maintaining integrity with a permanent synthetic support. This configuration is designed to stimulate fibroblast migration in addition to cell signaling cascades, leading to neovascularization and deposition of collagen (5). The biologic material from the ovine rumen reduces foreign body response, enable functional tissue remodeling and promote a natural repair. The interwoven and embroidered polymer fibers provide permanent reinforcement, along with improved handling and load-sharing capability.

With the introduction of biomaterials for reconstruction, the possibility of contamination of the patch is less likely as shown in the abdominal literature (5). In an earlier series by Miller et al, use of a non-crossed-linked bovine pericardium and absorbable PLA bars proved to be satisfactory; especially in infected cases (6). The principal goal of a combination material is to establish a scaffold for tissue ingrowth in addition to maintaining integrity with a permanent synthetic support. This configuration is designed to stimulate fibroblast migration in addition to cell signaling cascades, leading to neovascularization and deposition of collagen (7). This case describes the first use of a new biosynthetic material for CWR that is composed of ovineextracellular matrix and monofilament polypropylene sutures. The biologic material from ovine rumen reduces foreign body response, enable functional tissue remodeling and promote a natural repair. The polymer fibers provide interwoven permanent reinforcement, along with improved handling and loadsharing capability to support normal CW mechanics. BSM was first introduced for inguinal hernia repair, but the material has been employed in all soft tissue areas of the body for reconstruction support and repair (8). Since this case we have performed twenty-nine other CWRs for both benign and malignant indications using the BSM. This combination of BSMs appears to more stable with improved integrity of the chest, especially in areas of increased

excursion (lower chest) than the PLA bars and bovine pericardial patch for larger defects.

#### Conclusion

The key to a successful outcome in this complex case was the coordinated effort by the surgical teams individualizing the patient's care with total resection of the disease process, reconstruction of the chest wall, and restoration of nearnormal chest and upper abdomen anatomy and function. Chest wall reconstruction with BSM is both safe and effective. Long term follow-up is warranted.

#### References

- 1. SJ Ferzoco, Early experience outcome of reinforced bioscaffold in inguinal hernia repair; a case series. Int J Surg Open 2018; 12:9-11.
- 2. Alaedeen DI, Lipman J, Medalie D, et al. The single stage approach to the surgical management of abdominal wall hernias in contaminated fields. Hernia. 2007; 11:41-45.
- 3. Miller DL, Mansour KA. Chest Wall Reconstruction. Shield's Textbook of General Thoracic Surgery. Seventh. Thomas W. Shields. Lippincott Williams & Wilkins. Vol 1, 679-687, 2009.
- 4. Mansour KA, Thourani VH, Losken A, et al. Chest wall resections and reconstruction: A 25-year experience. Ann Thorac Surg 2002;73: 1720-1726.
- 5. MJ Parker, RC Kim, M Barrio, et al. A novel biosynthetic scaffold mesh reinforcement affords the lowest hernia recurrence in the highest-risk patients. Surg Endos 2021; 35:5173-5178.
- 6. Miller DL, Force SD, Pickens A, et al. Chest Wall Reconstruction Using Biomaterials. Ann Thorac Surg 2013; 95:1050–1056.
- 7. N Overbeck, GM Nagvajara, S Ferzoco, et al. In Vivo evaluation of reinforced ovine biologic; a comparative study to available hernia mesh repair materials. Hernia 2020:24:1293-1306.
- 8. Wiegmann B, Korossis S, Burgwitz K, et al. Invitro comparison of biological and synthetic materials for skeletal chest.

J Sur Re Rep, 2022 Volume 1 (3) | 4 of 5